



Assembly Instructions





A

M8*210

x4

Diagram A shows a long screw with a hexagonal head and a threaded shaft. The specifications are M8*210 and the quantity is x4.

B

8#

x1

Diagram B shows a hexagonal nut and a short screw. The specifications are 8# and the quantity is x1.

C

M8

x4

Diagram C shows a hexagonal nut. The specifications are M8 and the quantity is x4.





D

80*80



x4

Diagram D shows a square plate. The specifications are 80*80 and the quantity is x4.


1



2



3



OK